



**JEFFERSON COUNTY OFFICE OF EMERGENCY MANAGEMENT**  
\*\*\*\*\*  
**DONNA HAUGOM, DIRECTOR**  
**TRACY NEUHAUSER, INTERIM DIRECTOR**

DATE: January 16, 2024

FROM: Tracy Neuhauser

SUBJECT: Request for Proposal

Jefferson County has received Grant Funding to acquire and demolish 1 property at W7696 Blackhawk Island Road, Fort Atkinson WI 53538 as part a Flood Mitigation and Acquisition Program. We are currently requesting proposals for services related to the demolition of this property.

The proposal should include demolition, capping the well and abandonment of septic system, along with asbestos abatement. Jefferson County will have the asbestos and lead inspections completed prior to demolition. Jefferson County will also ensure that the Gas/Electrical will be disconnected prior to the demolition.

The asbestos abatement will include the following:

- Complete documentation of the project.
- Filing of notice forms to DNR/DHS as applicable.
- Asbestos Notice fees paid in full as required by DNR/DHS
- Work area/abatement procedures/work force will meet or exceed State, EPA and OSHA regulations/specifications
- Handling/disposal of waste material to a DNR approved landfill.

The demolition work will include the following:

- Submit DNR notice for demolition and pull local demolition permit.
- Abandon well and septic systems – complete closure paperwork.
- Removal and proper disposal of universal wastes and appliances.
- Removal of paved driveway.
- Protect roads from damage and comply with local road weight postings.
- Demolition and removal of all building materials and contents from the footprint of the buildings.
- Materials shall be recycled, salvaged, or properly disposed of. Materials not recycled or salvaged shall be disposed of at a C&D landfill and properly documented. Any salvage value from the building would become the property of the demolition contractor.
- Concrete, brick and block materials will be hauled off site and used as clean fill.
- Back fill basement with compacted fill, grade site and seed disturbed area.

All services must be compliant with FEMA, State Regulations, and DNR Standards.

Please attach a fee schedule detailing your fees for the services identified.

If you should have any questions, please feel free to contact me at 920-674-8674 or via e-mail at [tracyn@jeffersoncountywi.gov](mailto:tracyn@jeffersoncountywi.gov).

Your response is expected no later than the close of business on January 30, 2024. Please e-mail your response to [tracyn@jeffersoncountywi.gov](mailto:tracyn@jeffersoncountywi.gov)

Thank you in advance for your time and I look forward to receiving your proposal.

**107 E. Washington Street Jefferson WI 53549 920-674-7450**  
**[dannah@jeffersoncountywi.gov](mailto:dannah@jeffersoncountywi.gov) / [tracyn@jeffersoncountywi.gov](mailto:tracyn@jeffersoncountywi.gov)**



**Environmental Management Consulting, Inc.**

**NESHAP'S PRE-DEMOLITION ASBESTOS INSPECTION**

**VACANT RESIDENCE  
W7696 BLACKHAWK ISLAND ROAD  
FORT ATKINSON, WI 53538**

**INSPECTION DATE: JANUARY 9, 2024  
REPORT DATE: JANUARY 15, 2024  
EMC PROJECT NUMBER: 230292-01**

**PREPARED FOR:**

**JEFFERSON COUNTY EMERGENCY MANAGEMENT  
107 E. Washington Street  
JEFFERSON, WI 53549**

**PREPARED BY:**

**MR. THOMAS J. BUSHMAN  
ENVIRONMENTAL MANAGEMENT CONSULTING, INC.  
W7748 COUNTY HIGHWAY V  
LAKE MILLS, WI 53551**

*Securing Safer Futures...*

W 7748 Cty Hwy V, Lake Mills, WI 53551 ◆ 920.648.6343 Fax: 920.648-4370 ◆ [www.emc-wi.com](http://www.emc-wi.com)

## **TABLE OF CONTENTS**

<b>SECTION I</b>	<b>EXECUTIVE SUMMARY</b>
<b>SECTION II</b>	<b>ASBESTOS SURVEY &amp; SAMPLE RESULTS</b>
<b>SECTION III</b>	<b>CERTIFICATIONS</b>

**SECTION I**  
**EXECUTIVE SUMMARY**

## **EXECUTIVE SUMMARY**

Environmental Management Consulting, Inc. (EMC) was contacted by Donna Haugom of Jefferson County Emergency Management to conduct an asbestos pre-demolition survey of W7696 Blackhawk Island Road, Fort Atkinson, WI.

Mr. Thomas J. Bushman of EMC inspected the subject property on January 9, 2024. The building was inspected for the presence of asbestos containing building materials. Bulk samples were extracted for each building material found suspect to contain asbestos. All samples were submitted to a NVLAP certified laboratory for analysis. This report will summarize the findings of this inspection.

All bulk sampling information, including a bulk sample chart and the laboratory results, are attached to this report. Please contact the EMC office if you have any questions.

A handwritten signature in black ink, appearing to read "Thomas J. Bushman", with a long, sweeping underline.

Thomas J. Bushman  
Certification: All-208554

**SECTION II**  
**ASBESTOS SURVEY & SAMPLE RESULTS**

## NESHAP'S ASBESTOS PRE-DEMOLITION INSPECTION

### **CATEGORY I & CATEGORY II, NON-FRIABLE ACM**

The following is a summary of materials identified or assumed to contain asbestos that were assessed as non-friable materials.

#### **SINK UNDERCOATING – MSU**

<u>Room/Location</u>	<u>Quantity</u>	<u>Asbestos Status</u>
Kitchen	1 Sink	2% Chrysotile Asbestos

#### **FOUNDATION TAR ON BLOCK – MFT**

<u>Room/Location</u>	<u>Quantity</u>	<u>Asbestos Status</u>
Exterior of House	240 Sq. Ft.	5% Chrysotile Asbestos

At the time of inspection, the above stated materials were assessed in a good condition. Non-friable ACM does not have to be removed prior to a normal demolition if it is not in poor condition prior to starting the demolition and is not likely to become friable during demolition activities. The resulting wastes can be handled as demolition material; contact the accepting landfill. If the demolition materials will be recycled, all ACM must be removed prior to the demolition. Furthermore, if the ACM becomes crumbled, pulverized or reduced to powder as a result of demolition practices, all materials must be treated as RACM including those demolition materials co-mingled with the RACM.

If this building is to be burned as a practice fire burn by the fire department, all non-friable ACM would have to be removed prior to burning.

#### **REMAINING NON-FRIABLE MATERIALS**

Unless otherwise indicated, all caulking, sealants, glazing compounds, gaskets, asphalt roofing materials, fillers, mastics and miscellaneous adhesives are assumed to contain asbestos and were assessed to be non-friable ACM as defined in NR 447. At the time of this inspection these materials were not in poor condition and were not friable. If work methods cause non-friable ACM to become friable, the materials must be treated as RACM.

## **NON-ASBESTOS MATERIALS**

The following is a summary of materials which have been sampled by Polarized Light Microscopy, EPA Method: 600/R-93/116 and found not to contain asbestos.

<u>Material Code</u>	<u>Material Description</u>
MVFT1	Vinyl Floor Tile (White) and Underlayment (Kitchen)
MVFT2	Vinyl Floor Tile (Gray) and Underlayment (Bathroom)
MPA	Paneling Adhesive (Bathroom)
MBI	Blown-in Insulation (Attic)
MFB	Fiberboard (Attic)
MRS	Roof Shingles and Felt Paper (House Roof)
MFP	Felt Paper Behind Wood Siding (House Exterior)
MRSG	Roof Shingles (Garage Roof)
MSSG	Roof Shingle Siding (Garage Exterior)
MFBG	Fiberboard Insulation (Garage Interior)
MPGIG	Interior Window Glazing Compound (Garage Interior)
MRSS	Roof Shingles and Felt Paper (Shed Roof)
MDW1	Drywall & Joint Compound

No work is necessary for these materials.

## **ADDITIONAL REQUIREMENTS**

Prior to the demolition or burning of any structure, a "Notification of Demolition and/or Renovation and Application for Exemption" (Form 4500-113) must be submitted to the Wisconsin Department of Natural Resources. Residential property as defined by DNR Chapter 447 may be exempt from notification requirements. If asbestos removal is necessary a copy of the notification must be submitted to the Wisconsin Department of Health Services. The owner/operator is responsible for submitting all notifications. Removal of any asbestos containing material must be completed by persons certified by the Department of Health Services.

If during the course of demolition, suspect materials are found that have not been identified or sampled, work must stop and a State of Wisconsin certified Asbestos Building Inspector must be contacted to assess the material. There are inaccessible areas within the building that could not be accessed during the inspection, which could result in additional suspect material discovered.

Exceptions to asbestos certification include an individual who operates a motorized vehicle to demolish or remove a facility when asbestos-containing material is allowed to remain in the building during demolition. All other works in the demolition work site must have certification complying with DHS 159.05. Demolition contractors shall follow all DHS regulations.

All bulk sampling information, including a bulk sample chart and the laboratory results, are attached to this report. Please contact the EMC office if you have any questions.



## **ASBESTOS BULK SAMPLE RESULTS**

## ASBESTOS BULK SAMPLE CHART

Sampling Date: January 9, 2024  
 Sample Location: W7696 Blackhawk Island Rd, Fort Atkinson, WI  
 Sampling Personnel: Thomas J. Bushman

EMC Project Number: 230292-01  
 Inspector Number: All-208554

SAMPLE NUMBER	HOMO CODE	MATERIAL DESCRIPTION	ROOM/ AREA	SPECIFIC SAMPLE LOCATION	LAB RESULTS
B-01	MDW1	Drywall & Joint Compound	South Bedroom	East Wall	No Asbestos Detected
B-02	MDW1	Drywall & Joint Compound	Bathroom	South Wall	No Asbestos Detected
B-03	MSU	Sink Undercoating	Kitchen	Below Sink	2% Chrysotile Asbestos
B-04	MVFT1	Vinyl Floor Tile (White) & Underlayment	Kitchen	Center of Room	No Asbestos Detected
B-05	MVFT1	Vinyl Floor Tile (White) & Underlayment	Kitchen	Near Living Room	No Asbestos Detected
B-06	MVFT2	Vinyl Floor Tile (Gray) & Underlayment	Bathroom	At Entrance	No Asbestos Detected
B-07	MVFT2	Vinyl Floor Tile (Gray) & Underlayment	Bathroom	Center of Room	No Asbestos Detected
B-08	MPA	Paneling Adhesives	Bathroom	East Wall	No Asbestos Detected
B-09	MPA	Paneling Adhesives	Bathroom	South Wall	No Asbestos Detected
B-10	MBI	Blown-In Insulation	Attic	At Entrance	No Asbestos Detected
B-11	MBI	Blown-In Insulation	Attic	At Entrance	No Asbestos Detected
B-12	MFB	Fiberboard	Attic	At Entrance	No Asbestos Detected
B-13	MFB	Fiberboard	Attic	At Entrance	No Asbestos Detected
B-14	MRS	Roof Shingles & Felt Paper	House Roof	Roof	No Asbestos Detected
B-15	MRS	Roof Shingles & Felt Paper	House Roof	Roof	No Asbestos Detected
B-16	MFP	Felt Paper Below Wood Siding	Exterior of House	West Side	No Asbestos Detected
B-17	MFP	Felt Paper Below Wood Siding	Exterior of House	West Side	No Asbestos Detected
B-18	MFT	Foundation Tar on Block	Exterior of House	West Side	5% Chrysotile Asbestos
B-19	MFT	Foundation Tar on Block	Exterior of House	South Side	5% Chrysotile Asbestos
B-20	MRSG	Roof Shingles	Exterior of Garage	Roof	No Asbestos Detected
B-21	MRSG	Roof Shingles	Exterior of Garage	Roof	No Asbestos Detected
B-22	MSSG	Roof Shingle Siding	Exterior of Garage	East Side	No Asbestos Detected
B-23	MSSG	Roof Shingle Siding	Exterior of Garage	East Side	No Asbestos Detected
B-24	MFBG	Fiberboard Insulation	Interior of Garage	West Side	No Asbestos Detected
B-25	MFBG	Fiberboard Insulation	Interior of Garage	East Side	No Asbestos Detected



Environmental Management Consulting, Inc.

# ASBESTOS BULK SAMPLE CHART

Sampling Date: January 9, 2024

Sample Location: W7696 Blackhawk Island Rd, Fort Atkinson, WI

Sampling Personnel: Thomas J. Bushman

EMC Project Number: 230292-01

Inspector Number: AII-208554

SAMPLE NUMBER	HOMO CODE	MATERIAL DESCRIPTION	ROOM/ AREA	SPECIFIC SAMPLE LOCATION	LAB RESULTS
B-26	MPGIG	Interior Window Glazing Compound	Interior of Garage	West Side	No Asbestos Detected
B-27	MPGIG	Interior Window Glazing Compound	Interior of Garage	West Side	No Asbestos Detected
B-28	MRSS	Roof Shingles & Felt Paper	Exterior of Shed	Roof	No Asbestos Detected
B-29	MRSS	Roof Shingles & Felt Paper	Exterior of Shed	Roof	No Asbestos Detected




Environmental Management Consulting, Inc.

W7748 County Highway V, Lake Mills, WI ■ Phone: 920.648.6343 Fax: 920.648.4370 ■ [www.emc-wi.com](http://www.emc-wi.com)



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and  
40 CFR, Part 763, Subpart E, App.E



**Customer:** Environmental Management Consulting, Inc. **Attn:** Thomas Bushman  
W7748 Cnty Hwy V  
Lake Mills, WI 53551

**Lab Order ID:** 10040739  
**Analysis:** PLM  
**Date Received:** 01/10/2024  
**Date Reported:** 01/15/2024

**Project:** 230292-01/Pre-Demo W7696 Blackhawk  
Island Rd

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
B-01 - A	Drywall and joint compound	None Detected	20% Cellulose	80% Gypsum	Brown, Gray Fibrous Heterogeneous
10040739_0001	<i>drywall</i>				Dissolved
B-01 - B	Drywall and joint compound	None Detected		100% Calcium	White Non-Fibrous Homogeneous
10040739_0030	<i>joint compound</i>				Dissolved
B-01 - C	Drywall and joint compound	None Detected	20% Cellulose	70% Gypsum 10% Calcium	Gray, White Fibrous Heterogeneous
10040739_0031	<i>composite</i>				Dissolved
B-02 - A	Drywall and joint compound	None Detected	20% Cellulose	80% Gypsum	Brown, Gray Fibrous Heterogeneous
10040739_0002	<i>drywall</i>				Dissolved
B-02 - B	Drywall and joint compound	None Detected		100% Calcium	White Non-Fibrous Homogeneous
10040739_0032	<i>joint compound</i>				Dissolved
B-02 - C	Drywall and joint compound	None Detected	20% Cellulose	70% Gypsum 10% Calcium	White, Brown Fibrous Heterogeneous
10040739_0033	<i>composite</i>				Dissolved
B-03	Sink undercoating	2% Chrysotile		98% Other	Gray Fibrous Homogeneous
10040739_0003					Dissolved
B-04 - A	Vinyl floor tile (white) and underlayment	None Detected		100% Other	Gray Non-Fibrous Homogeneous
10040739_0004	<i>vinyl floor tile</i>				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogenous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Patrick Yarnell (44)

Analyst

Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and  
40 CFR, Part 763, Subpart E, App.E



**Customer:** Environmental Management Consulting, Inc. **Attn:** Thomas Bushman  
W7748 Cnty Hwy V  
Lake Mills, WI 53551

**Lab Order ID:** 10040739  
**Analysis:** PLM  
**Date Received:** 01/10/2024  
**Date Reported:** 01/15/2024

**Project:** 230292-01/Pre-Demo W7696 Blackhawk  
Island Rd

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
B-04 - B	Vinyl floor tile (white) and underlayment	None Detected	60% Cellulose 10% Fiber Glass	30% Other	Tan Fibrous Homogeneous
10040739_0034	underlayment				Dissolved, Ashed
B-05 - A	Vinyl floor tile (white) and underlayment	None Detected		100% Other	Black Non-Fibrous Homogeneous
10040739_0005	vinyl floor tile				Dissolved
B-05 - B	Vinyl floor tile (white) and underlayment	None Detected	60% Cellulose 10% Fiber Glass	30% Other	Tan Fibrous Homogeneous
10040739_0035	underlayment				Dissolved, Ashed
B-06 - A	Vinyl floor tile (gray) and underlayment	None Detected		100% Other	Gray Non-Fibrous Homogeneous
10040739_0006	vinyl floor tile				Dissolved
B-06 - B	Vinyl floor tile (gray) and underlayment	None Detected		100% Other	Yellow Non-Fibrous Homogeneous
10040739_0036	mastic				Dissolved
B-06 - C	Vinyl floor tile (gray) and underlayment	None Detected		100% Other	Gray Non-Fibrous Homogeneous
10040739_0037	underlayment				Dissolved
B-07 - A	Vinyl floor tile (gray) and underlayment	None Detected		100% Other	Gray Non-Fibrous Homogeneous
10040739_0007	vinyl floor tile				Dissolved
B-07 - B	Vinyl floor tile (gray) and underlayment	None Detected		100% Other	Yellow Non-Fibrous Homogeneous
10040739_0038	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogenous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Patrick Yarnell (44)

Analyst

Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
 EPA Method: 600/R-93/116 and  
 40 CFR, Part 763, Subpart E, App.E



**Customer:** Environmental Management Consulting, Inc. **Attn:** Thomas Bushman  
 W7748 Cnty Hwy V  
 Lake Mills, WI 53551

**Lab Order ID:** 10040739

**Analysis:** PLM

**Date Received:** 01/10/2024

**Date Reported:** 01/15/2024

**Project:** 230292-01/Pre-Demo W7696 Blackhawk  
 Island Rd

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
B-07 - C	Vinyl floor tile (gray) and underlayment	None Detected		100% Other	Gray Non-Fibrous Homogeneous
10040739_0039	underlayment				Dissolved
B-08	Paneling adhesive	None Detected		100% Other	Yellow Non-Fibrous Homogeneous
10040739_0008					Dissolved
B-09	Paneling adhesive	None Detected		100% Other	Yellow Non-Fibrous Homogeneous
10040739_0009					Dissolved
B-10	Blown-in insulation	None Detected	99% Mineral Wool	1% Other	Tan Fibrous Homogeneous
10040739_0010					Teased
B-11	Blown-in insulation	None Detected	99% Mineral Wool	1% Other	Tan Fibrous Homogeneous
10040739_0011					Teased
B-12	Fiberboard	None Detected	99% Cellulose	1% Other	Brown Fibrous Homogeneous
10040739_0012					Teased
B-13	Fiberboard	None Detected	99% Cellulose	1% Other	Brown Fibrous Homogeneous
10040739_0013					Teased
B-14 - A	Roof shingles and felt paper	None Detected	20% Fiber Glass	70% Other 10% Quartz	Black Fibrous Heterogeneous
10040739_0014	shingle				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogenous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Patrick Yarnell (44)

Analyst

Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and  
40 CFR, Part 763, Subpart E, App.E



**Customer:** Environmental Management Consulting, Inc. **Attn:** Thomas Bushman  
W7748 Cnty Hwy V  
Lake Mills, WI 53551

**Lab Order ID:** 10040739  
**Analysis:** PLM  
**Date Received:** 01/10/2024  
**Date Reported:** 01/15/2024

**Project:** 230292-01/Pre-Demo W7696 Blackhawk  
Island Rd

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
B-14 - B	Roof shingles and felt paper	None Detected	30% Cellulose	70% Other	Black Non-Fibrous Homogeneous
10040739_0040	felt paper				Dissolved
B-15 - A	Roof shingles and felt paper	None Detected	20% Fiber Glass	70% Other 10% Quartz	Black Fibrous Heterogeneous
10040739_0015	shingle				Dissolved
B-15 - B	Roof shingles and felt paper	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous
10040739_0041	felt paper				Dissolved
B-16	Felt paper below wood siding	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous
10040739_0016					Dissolved
B-17	Felt paper below wood siding	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous
10040739_0017					Dissolved
B-18	Foundation tar on block	5% Chrysotile		95% Other	Black Fibrous Homogeneous
10040739_0018					Dissolved
B-19	Foundation tar on block	5% Chrysotile		95% Other	Black Fibrous Homogeneous
10040739_0019					Dissolved
B-20	Roof shingles	None Detected	20% Fiber Glass	70% Other 10% Quartz	Black Fibrous Heterogeneous
10040739_0020					Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogenous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Patrick Yarnell (44)

Analyst

Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and  
40 CFR, Part 763, Subpart E, App.E



**Customer:** Environmental Management Consulting, Inc. **Attn:** Thomas Bushman  
W7748 Cnty Hwy V  
Lake Mills, WI 53551

**Lab Order ID:** 10040739  
**Analysis:** PLM  
**Date Received:** 01/10/2024  
**Date Reported:** 01/15/2024

**Project:** 230292-01/Pre-Demo W7696 Blackhawk  
Island Rd

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
B-21	Roof shingles	None Detected	20% Fiber Glass	70% Other 10% Quartz	Black Fibrous Heterogeneous
10040739_0021					Dissolved
B-22	Roof shingles siding	None Detected	30% Cellulose	60% Other 10% Quartz	Black Fibrous Heterogeneous
10040739_0022					Dissolved
B-23 - A	Roof shingles siding	None Detected	30% Cellulose	60% Other 10% Quartz	Black Fibrous Heterogeneous
10040739_0023	shingle				Dissolved
B-23 - B	Roof shingles siding	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous
10040739_0042	felt paper				Dissolved
B-24	Fiberboard insulation	None Detected	99% Cellulose	1% Other	Tan Fibrous Homogeneous
10040739_0024					Dissolved, Teased
B-25	Fiberboard insulation	None Detected	99% Cellulose	1% Other	Tan Fibrous Homogeneous
10040739_0025					Dissolved, Teased
B-26	Interior window glazing compound (garage windows)	None Detected		100% Other	Gray Non-Fibrous Homogeneous
10040739_0026					Ashed, Dissolved
B-27	Interior window glazing compound (garage windows)	None Detected		100% Other	Gray Non-Fibrous Homogeneous
10040739_0027					Dissolved, Ashed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogenous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Patrick Yarnell (44)

Analyst

Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and  
40 CFR, Part 763, Subpart E, App.E



**Customer:** Environmental Management Consulting, Inc. **Attn:** Thomas Bushman  
W7748 Cnty Hwy V  
Lake Mills, WI 53551

**Lab Order ID:** 10040739

**Analysis:** PLM

**Date Received:** 01/10/2024

**Date Reported:** 01/15/2024

**Project:** 230292-01/Pre-Demo W7696 Blackhawk  
Island Rd

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
B-28 - A	Roof shingles and felt paper	None Detected	20% Fiber Glass	70% Other 10% Quartz	Black Fibrous Heterogeneous
10040739_0028	shingle				Dissolved
B-28 - B	Roof shingles and felt paper	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous
10040739_0043	felt paper				Dissolved
B-29 - A	Roof shingles and felt paper	None Detected	20% Fiber Glass	70% Other 10% Quartz	Black Fibrous Heterogeneous
10040739_0029	shingle				Dissolved
B-29 - B	Roof shingles and felt paper	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous
10040739_0044	felt paper				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogenous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Patrick Yarnell (44)

Analyst

Approved Signatory



Environmental Management Consulting, Inc.

<b>E.M.C., Inc.</b> W7748 County Highway V Lake Mills, WI 53551 920-648-6343	<b>Scientific Analytical Institute</b> 4604 Dundas Drive Greensboro, NC 27407 877-292-3888
---------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------

Lab Order ID: 10040739



EMC Contact: Thomas J. Bushman	<b>Test Type</b>	<b>Turnaround Time</b>	
Email : emc@emc-wi.com	PLM <input checked="" type="checkbox"/>	12 Hours <input type="checkbox"/>	120 Hours <input type="checkbox"/>
Sample Location: W7696 Blackhawk Island Rd	Point Count <input type="checkbox"/>	24 Hours <input type="checkbox"/>	144+ Hours <input type="checkbox"/>
Sample Date: 1-9-24 Fort Atkinson, WI	PCM <input type="checkbox"/>	48 Hours <input type="checkbox"/>	
Sampling Personnel: Thomas J. Bushman	TEM <input type="checkbox"/>	72 Hours <input checked="" type="checkbox"/>	
Inspector Number: AII-208554	Lead <input type="checkbox"/>	96 Hours <input type="checkbox"/>	
Project Name/ #: 230292-01 / Pre-Demo W7696 Blackhawk Island Rd			

Sample Number	Homo Code	SR/JC:	Enter Into Laboratory "Sample Description" Field			Lab Results
			Material Description	Room	Specific Location or Volume/Area	
B-01	MDWI	<input type="checkbox"/>	Drywall and joint compound	South Bedroom	East Wall	
B-02	↓	<input type="checkbox"/>	↓	Bathroom	South Wall	
B-03	MSU	<input type="checkbox"/>	sink Undercoating	Kitchen	Below sink	
B-04	MVFT1	<input type="checkbox"/>	Vinyl Floor tile (white) and Underlayment	Kitchen	Center of Room	
B-05	↓	<input type="checkbox"/>	↓	↓	Near livingroom	
B-06	MVFT2	<input type="checkbox"/>	Vinyl Floor tile (gray) and Underlayment	Bathroom	At Entrance	
B-07	↓	<input type="checkbox"/>	↓	↓	Center of Room	
B-08	MPA	<input type="checkbox"/>	Paneling Adhesive	Bathroom	East Wall	
B-09	↓	<input type="checkbox"/>	↓	↓	South Wall	
B-10	MBI	<input type="checkbox"/>	Blown-in Insulation	Attic	At Entrance	
B-11	↓	<input type="checkbox"/>	↓	↓	↓	
B-12	MFB	<input type="checkbox"/>	Fiberboard	↓	↓	
B-13	↓	<input type="checkbox"/>	↓	↓	↓	
B-14	MRS	<input type="checkbox"/>	Roof Shingles and Felt paper	House Roof	Roof	
B-15	↓	<input type="checkbox"/>	↓	↓	↓	
B-16	MFP	<input type="checkbox"/>	Felt paper Below	Exterior of House	West side	
B-17	↓	<input type="checkbox"/>	Wood Siding	↓	↓	
B-18	MFT	<input type="checkbox"/>	Foundation Tar on Block	↓	West side	Accepted <input checked="" type="checkbox"/>
B-19	↓	<input type="checkbox"/>	↓	↓	South side	Rejected <input type="checkbox"/>
B-20	MRSG	<input type="checkbox"/>	Roof Shingles and Felt paper	Exterior of Garage	Roof	

Total # of Samples 20

<b>Relinquished by</b> <i>[Signature]</i>	<b>Date/Time</b> 1-9-24	<b>Received by</b> <i>[Signature]</i>	<b>Date/Time</b> 1/10/24 10:30am
----------------------------------------------	----------------------------	------------------------------------------	-------------------------------------

Please Email To:

- bfreeman@emc-wi.com
- jrbushman@emc-wi.com
- jjozwiakowski@emc-wi.com
- amaule@emc-wi.com
- proche@emc-wi.com
- jschneider@emc-wi.com
- rhaveman@emc-wi.com
- cfreeman@emc-wi.com
- jnoegel@emc-wi.com
- mfreeman@emc-wi.com
- twinslow@emc-wi.com
- tbushman@emc-wi.com
- jharman@emc-wi.com
- emc@emc-wi.com

Page 1 of 2



**SECTION III**  
**CERTIFICATIONS**

ASBESTOS PROJ. DESIGNER  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
William A. ...  
190 lbs 6' 00"

AMP-1284	Exp: 03/31/2024	03/08/1964
----------	-----------------	------------

Training due by: 03/31/2024

ASBESTOS SUPERVISOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
William A. ...  
190 lbs 6' 00"

ACS-1284	Exp: 05/10/2024	03/08/1964
----------	-----------------	------------

Training due by: 05/10/2024

ASBESTOS INSPECTOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
William A. ...  
190 lbs 6' 00"

All-1284	Exp: 03/31/2024	03/08/1964
----------	-----------------	------------

Training due by: 03/31/2024

ASBESTOS PROJ. DESIGNER  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
John ...  
195 lbs 5' 10"

AMP-1283	Exp: 03/28/2024	03/03/1965
----------	-----------------	------------

Training due by: 03/28/2024

ASBESTOS MGMT. PLANNER  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
John ...  
195 lbs 5' 10"

AMP-1283	Exp: 03/28/2024	03/03/1965
----------	-----------------	------------

Training due by: 03/28/2024

ASBESTOS SUPERVISOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
John ...  
195 lbs 5' 10"

ACS-1283	Exp: 04/26/2024	03/03/1965
----------	-----------------	------------

Training due by: 04/26/2024

ASBESTOS INSPECTOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
John ...  
195 lbs 5' 10"

All-1283	Exp: 03/28/2024	03/03/1965
----------	-----------------	------------

Training due by: 03/28/2024

ASBESTOS MGMT. PLANNER  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
James P. ...  
170 lbs 5' 10"

AMP-1214	Exp: 03/20/2024	10/04/1965
----------	-----------------	------------

Training due by: 03/20/2024

ASBESTOS SUPERVISOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
James P. ...  
170 lbs 5' 10"

ACS-1214	Exp: 03/04/2024	10/04/1965
----------	-----------------	------------

Training due by: 03/04/2024

ASBESTOS INSPECTOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
James P. ...  
170 lbs 5' 10"

All-1214	Exp: 03/15/2024	10/04/1965
----------	-----------------	------------

Training due by: 03/15/2024

ASBESTOS SUPERVISOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Jason G. ...  
220 lbs 6' 01"

ACS-14552	Exp: 03/21/2024	02/04/1971
-----------	-----------------	------------

Training due by: 03/21/2024

ASBESTOS INSPECTOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Jason G. ...  
220 lbs 6' 01"

All-14552	Exp: 03/20/2024	02/04/1971
-----------	-----------------	------------

Training due by: 03/20/2024

ASBESTOS SUPERVISOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Lance ...  
185 lbs 6' 00"

ACS-105450	Exp: 03/21/2024	02/19/1977
------------	-----------------	------------

Training due by: 03/21/2024

ASBESTOS INSPECTOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Lance ...  
185 lbs 6' 00"

All-105450	Exp: 03/20/2024	02/19/1977
------------	-----------------	------------

Training due by: 03/20/2024

ASBESTOS SUPERVISOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Matthew ...  
180 lbs 5' 09"

ACS-121592	Exp: 03/10/2024	03/19/1987
------------	-----------------	------------

Training due by: 03/10/2024

ASBESTOS INSPECTOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Matthew ...  
180 lbs 5' 09"

All-121592	Exp: 03/08/2024	03/19/1987
------------	-----------------	------------

Training due by: 03/15/2024

ASBESTOS SUPERVISOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Thomas ...  
150 lbs 5' 09"

ACS-208554	Exp: 03/28/2024	04/15/1993
------------	-----------------	------------

Training due by: 03/28/2024

ASBESTOS INSPECTOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Thomas ...  
150 lbs 5' 09"

All-208554	Exp: 10/28/2024	04/15/1993
------------	-----------------	------------

Training due by: 10/28/2024

ASBESTOS SUPERVISOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Christina ...  
160 lbs 5' 10"

ACS-229815	Exp: 03/03/2024	04/22/1997
------------	-----------------	------------

Training due by: 03/03/2024

ASBESTOS INSPECTOR  
Issued By  
STATE OF WISCONSIN  
Dept. of Health Services  
Christina ...  
160 lbs 5' 10"

All-229815	Exp: 11/12/2024	04/22/1997
------------	-----------------	------------

Training due by: 11/12/2024

**ASBESTOS SUPERVISOR**  
 Issued By  
 STATE OF WISCONSIN  
 Dept. of Technical Services  
 Abbie [Name]  
 License No. [Number]-9643

ACS-241993	Exp: 03/04/2024	09/25/1997	165 lbs	5' 08"
------------	-----------------	------------	---------	--------

Training due by: 03/04/2024

**ASBESTOS INSPECTOR**  
 Issued By  
 STATE OF WISCONSIN  
 Dept. of Technical Services  
 Abbie [Name]  
 License No. [Number]-9643

AII-251993	Exp: 11/06/2024	09/25/1997	165 lbs	5' 08"
------------	-----------------	------------	---------	--------

Training due by: 11/06/2024

**ASBESTOS SUPERVISOR**  
 Issued By  
 STATE OF WISCONSIN  
 Dept. of Technical Services  
 [Name]  
 License No. [Number]-9643

ACS-285936	Exp: 04/15/2024	01/21/2000	130 lbs	5' 05"
------------	-----------------	------------	---------	--------

Training due by: 04/15/2024

**ASBESTOS INSPECTOR**  
 Issued By  
 STATE OF WISCONSIN  
 Dept. of Technical Services  
 [Name]  
 License No. [Number]-9643

AII-285936	Exp: 09/14/2024	01/21/2000	130 lbs	5' 05"
------------	-----------------	------------	---------	--------

Training due by: 09/14/2024

**ASBESTOS SUPERVISOR**  
 Issued By  
 STATE OF WISCONSIN  
 Dept. of Technical Services  
 [Name]  
 License No. [Number]-9643

ACS-291839	Exp: 05/26/2024	08/07/2001	215 lbs	6' 00"
------------	-----------------	------------	---------	--------

Training due by: 05/26/2024

**ASBESTOS SUPERVISOR**  
 Issued By  
 STATE OF WISCONSIN  
 Dept. of Technical Services  
 [Name]  
 License No. [Number]-9643

ACS-847	Exp: 03/24/2024	04/08/1965	185 lbs	6' 00"
---------	-----------------	------------	---------	--------

Training due by: 03/24/2024

**ASBESTOS INSPECTOR**  
 Issued By  
 STATE OF WISCONSIN  
 Dept. of Technical Services  
 [Name]  
 License No. [Number]-9643

AII-847	Exp: 03/26/2024	04/08/1965	185 lbs	6' 00"
---------	-----------------	------------	---------	--------

Training due by: 03/26/2024